

LGS INNOVATIONS LLC GSA SCHEDULE – GS-35F-0429L

PRODUCTS AND SERVICES PRICELIST

VIDEO TELECONFERENCING ELECTRONIC ROOM EQUIPMENT MAINTENANCE (132-12)

LGS Product Code	Description	Monthly GSA Maint Price	WTY Period
0301AA	EXECUTIVE ROOM CONFIGURATION MAINTENANCE consists of: Three (3) Monitors (incoming, outgoing, graphics); One (1) CODEC (Tandberg,Polycom); Five (5) Cameras (includes graphics system, i.e. Elmo EV-308, Elmo EV-368); Two (2) VCR; Control System (i.e., AMX {up to 2 touch panels}, Pan & Tilt Unit (1 or 2); Video Switcher (i.e. Dynair, Autopatch); Hardcopy Printer; Secure Switches (includes modems and cable up to but not including KG equipment); Non-Secure Switches (includes associated cable and equipment); Fiber Modems; Audio System (i.e. Coherent, Gentner); Mixers, Echo Cancellers, Bridging Equipment; Video and Audio Monitoring Devices (i.e. Line Monitor, Vector Scopes)	\$ 945.32	N/A
0301AB	MODULAR ROOM CONFIGURATION MAINTENANCE consists of: Two (2) Monitors (incoming, outgoing One(1) CODEC(Tandberg,Polycom);Three (3) Cameras; One (1) VCR; Control System (i.e., AMX); One (1) Pan & Tilt Unit; Video Switcher (i.e. Dynair, Autopatch); Secure Switches (includes modems and cable up to but not including KG equipment); Non-Secure Switches (includes associated cable and equipment); Fiber Modems; Audio System (i.e. Coherent, Gentner); Mixers, Echo Cancellers, Bridging Equipment; Video and Audio Monitoring Devices (i.e. Line Monitor, Vector Scopes)	\$ 613.21	N/A
0301AC	ROLLABOUT ROOM CONFIGURATION MAINTENANCE consists of: One (1) Monitor (incoming, outgoing, graphics); One (1) CODEC(Tandberg,Polycom); One (1) Camera; Control System (i.e., AMX); One (1) Pan & Tilt Unit; Video Switcher (i.e. Dynair, Autopatch); Secure Switches (includes modems and cable up to but not including KG equipment); Non-Secure Switches (includes associated cable and equipment); Fiber Modems; Audio System (i.e. Coherent, Gentner); Mixers, Echo Cancellers, Bridging Equipment;	\$ 227.25	N/A
0302AA	Color Projector (i.e. Barco)	\$ 328.34	N/A
0302AB	Coder/Decoder (CLI II/VP)	\$ 357.59	N/A
0302AJ	Coder/Decoder (Tandberg, Polycom)	\$ 221.65	N/A
0302AC	Additional Monitor (up to 35")	\$ 18.38	N/A
0302AD	Additional Monitor (35" and larger)	\$ 26.35	N/A
0302AE	Additional Camera	\$ 21.46	N/A
0302AF	VCR	\$ 4.90	N/A
0302AG	Graphics Camera (i.e. Elmo EV-308; Elmo EV-368)	\$ 15.32	N/A
0302AH	Hardcopy Printer	\$ 7.35	N/A
0302AK	Plasma Display Panel (42" and smaller)	\$ 120.61	N/A
0302AL	Plasma Display Panel (Larger than 42")	\$ 206.85	N/A
0302AM	Cassette Deck	\$ 6.02	N/A
0302AN	Inverse Multiplexer	\$ 145.49	N/A
0302AO	Basic Audio System	\$ 75.38	N/A
0302AP	Standard Audio System	\$ 100.51	N/A
0302AQ	Deluxe Audio System	\$ 141.72	N/A
0302AR	Basic Video System	\$ 360.84	N/A
0302AS	Standard Video System	\$ 473.37	N/A
0302AT	Deluxe Video System	\$ 522.61	N/A
0302AU	Standard Control System	\$ 186.94	N/A
0302AV	Deluxe Control System	\$ 322.61	N/A
0302AW	Standard Network System	\$ 94.47	N/A
0304AC	Site Survey - On-Site (One-Time Charge)	\$ 1,373.65	N/A
0300MAT	Maintenance - Material	\$ 1.00	N/A